ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 13 | Mallasandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0035, W0056, W0037, W0058 | NA | Lake View Layout |
| **Segment No.** | **Total Length (m)** | |
| 13/C-W0035/S112801 | 226.66 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 58.21 | 77.515990 | 13.059081 | 77.516467 | 13.058840 | SWD Drain | Dead End |
| 2 | 82.58 | 77.516446 | 13.058814 | 77.516108 | 13.058145 | 1st Cross | Dead End |
| 3 | 85.87 | 77.516145 | 13.058961 | 77.515839 | 13.058245 | 1st Cross | Dead End |

## Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Cmpernsive Developement Works In Ward No 13 | 9800000 | 2019 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2018 - 2019 | Others | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | | 013-19-000008 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/DD/WO/382/18-19 | 07/03/2019 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 30/06/2019 | 30/06/2020 | Yes |

## Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| RIDL | | 0.00 |
| **one No.** | **E-Mail ID** | |
| 6269999 | | |

02-13

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬಾಗಲಗುಂಟೆ
ಹೆಸರಘಟ್ಟ ಮುಖ್ಯರಸ್ತೆ, ಬೆಂಗಳೂರು-560073

DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0035, W0056, W0037, W0058

Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Krishnappa |
| **Date of Inspection** | **Remarks** | |
| 04/08/2019 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Doddaiah | 04/08/2019 | 30/09/2019 | |
| EE | Jayalingappa | 04/08/2019 | 30/09/2019 | |
| AEE | jayalinappa | 04/08/2019 | 30/09/2019 | |
| AE | Krishnappa | 04/08/2019 | 30/09/2019 | |
| AE | Krishnappa | 03/08/2019 | 12/07/2019 | |

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ಬೆಂಗಳೂರು
ಪೆಸರಘಟ್ಟ ಮುಖ್ಯರಸ್ತೆ, ಬೆಂಗಳೂರು-560 073

**Zone:** DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0035, W0056, W0037, W0058

Scanned by CamScanner